HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

MILL CREEK 2 AND 3 HYDROELECTRIC SYSTEMS, MILL CREEK 3 SANDBOX Mill Creek Yucaipa vicinity San Bernardino County California HAER No. CA-2272-J

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David G. De Vries, photographer, February-June 2008

David G. De Vries, photographer, February-June 2008	
CA-2272-J-1	LOOKING ALONG WATER TUNNEL TOWARDS MILL CREEK 3 SANDBOX. WATER ENTERS FROM THE INTAKE AT THE LEAF RAKE IN CENTER. VIEW TO NORTHWEST.
CA-2272-J-2	MILL CREEK 3 SANDBOX, FROM NORTHEAST CORNER. VIEW TO SOUTHWEST.
CA-2272-J-3	THREE GATES AT SANDBOX INTAKE, LOOKING TO THE NORTH. WATER ENTERS FROM THE RIGHT, MAKES A 90 DEGREE TURN TOWARDS THE FAR RIGHT, THEN ENTERS THE SETTLING CHAMBERS.
CA-2272-J-4	VIEW FROM SOUTHWEST CORNER OF MILL CREEK 3 SANDBOX, AT START OF THE MILL CREEK 3 FLOWLINE. WATER IS SPILLING INTO THE BYPASS CHUTE. A LINE OF SETTLING CHAMBER GATE CONTROL WHEELS CAN BE SEEN ON TOP OF WESTERN WALL OF SANDBOX.
CA-2272-J-5	WATER FLOWING INTO BYPASS CHUTE AT THE SOUTHWEST CORNER OF THE SANDBOX. ALSO SHOWN IS A PART OF THE WESTERN ELEVATION OF THE SANDBOX.
CA-2272-J-6	WEST ELEVATION, MILL CREEK 3 SANDBOX.
CA-2272-J-7	DETAIL, TUNNEL PORTAL AND LEAF RAKE AT INTAKE TO SANDBOX, NEAR ITS SOUTHEAST CORNER.
CA-2272-J-8	BYPASS CHUTE ON WESTERN EDGE OF SANDBOX, WHICH FEEDS WATER BACK TO MILL CREEK WHEN THE FLOWLINE IS NOT IN USE. VIEW TO NORTH, FROM SOUTHWEST CORNER OF SANDBOX.

